

# Oil Field Environmental Incident Summary

**Incident:** 20140906160908      **Date/Time of Notice:** 09/06/2014 16:09  
**Responsible Party:** CONTINENTAL RESOURCES, INC.  
**Well Operator:** CONTINENTAL RESOURCES, INC.  
**Well Name:** JERRY 5-8H  
**Field Name:** POE      **Well File #:** 26530  
**Date Incident:** 9/6/2014      **Time Incident:** 14:30      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 151      **Rng:** 100      **Sec:** 8      **Qtr:**  
**Location Description:**

**Submitted By:** Patrick Skillestad      **Received By:**  
**Contact Person:** Patrick Skillestad  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident** Valve/Piping Connection Leak

	Spilled	Units	Recovered	Units	Reported to NRC:	Followup	Units
Oil					No		
Brine							
Other	5	Barrels	5	Barrels			

**Description of Other Released Contaminant:**

Fresh water with surfactant.

**Inspected:**      **Written Report Received:**      **Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

20 ft x 20 ft

***Potential Environmental Impacts:***

Location soil

***Action Taken or Planned:***

Standing fluid was sucked and contaminated soil will be removed after rig is gone.

***Wastes Disposal Location:*** TBD

***Agencies Involved:***

***Updates***

---

***Date:*** 9/8/2014

***Status:*** Reviewed; O&G Lead

***Author:*** Espe, Brady

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to valve/piping connection leak, remained on location within the diking according to the report. NDIC retains oversight.